



**Notes**

- 1) To install GASMAX, slide gas detector sensor head into duct mount and tighten set screw
- 2) For calibration, loosen set screw and remove gas detector sensor from duct mount. Attach calibration cup and calibrate with zero and span gases as per manual instructions. Replace gas detector sensor head and retighten set screw.

GASMAX II Gas Monitor

12-0350 GP Duct Mount

10-32 Mounting screw and captive nut  
(customer-supplied) (4 plcs)

Customer-supplied enclosure  
Approximately 4" x 8" x 6"

Drill 2.375" hole for 12-0350  
Duct Mount

~1.25"

Air Flow

		8/6/09
GDS Corp 2513 Hwy 646 Santa Fe, Texas 77510 409-927-2980		
Vertical Sensor Duct Mount		
SIZE	PART / DRAWING NO.	REV.
C	GDS-DS-081109A	