MACURCO GAS DETECTORS

ND1-FCK

FIELD CALIBRATION KIT

CONTENTS OF THE KIT:

- 1. Gas Cylinder of nitrogen dioxide.
- 2. Gas regulator with white cap fitting.
- 3. These instructions.

AUTHORIZED DISTRIBUTOR: GasDetectorsUSA.com Houston, Texas USA sales@GasDetectorsUSA.com 832-615-3588

GENERAL INFORMATION:

The heart of the ND-1 is a microcomputer. It constantly monitors various internal operating parameters, the ambient temperature, and the Nitrogen Dioxide (NO₂) reading. The NO₂ reading is determined by measuring the voltage across an electro-chemical cell whose chemistry responds to NO₂. The microcomputer takes the NO₂ data, compensates it for temperature, and then compares this data to the alarm set point.

All ND-1 NO₂ Detectors are factory calibrated when they are shipped to the customer. This calibration should be within specifications for 6 months to a year. Some jurisdictions, local standards, or customer preferences require periodic recalibrations. This Kit provides the means to fit those requirements. Macurco recommends checking the operation of the ND-1 every six months, either through use of the procedures given in the operating instructions or this Field Calibration Kit.

WHERE TO DO THE CALIBRATION?

The ND-1 will need to be partially disassembled for this procedure. It will be easiest to do this on a bench in a work area. However, if two people are available, it can be done at the actual working location of the ND-1.

FIELD CALIBRATION PROCEDURE:

NOTE: The ND-1 must have been power continuously for a minimum of 72 hours before proceeding.

- 1. Open the access door of the ND-1 case.
- 2. Remove the two bottom screws that secure the interior faceplate, and swing the faceplate up.
- 3. Ensure that the digital display is "ON" before starting.
- 4. Turn both the "FAN" and "ALARM" adjustments fully clockwise before proceeding.
- 5. Connect a multimeter across R27 (directly left of the large chip), with the positive lead connected to the lead-end with the loop.
- 6. Adjust RA5 "ZERO" potentiometer (multiturn type) until the voltmeter reading is 0.00 +/- 0.10 Vdc.
- 7. Wait for the multimeter display to stabilize. Repeat steps 6 and 7 until the meter reading remains stable.
- 8. Assemble the gas cylinder to the regulator and the rest of the tubing. Turn-on the NO₂ regulator, and ensure that the tank pressure is sufficient to complete the calibration.
- 9. Place the white applicator attached to the regulator hose over the electrochemical cell, applying NO₂ to the sensor.
- 10. Wait for the meter reading and the display to respond this may take several minutes.

- 11. Wait 30 minutes, and then adjust the RA4 "GAIN" potentiometer (multiturn-type).
- 12. Note the gas mixture value in parts-per-million that is located on the label of the gas cylinder. Adjust the potentiometer (RA4) until the display reading matches the gas mixture being used to calibrate the unit.
- 13. Remove the NO₂ gas from the sensor, and remove the gas regulator from the cylinder.
- 14. Wait at least 1 hour on the first adjustment cycle. On subsequent adjustment cycles, this delay may be shortened to 15 minutes.
- 15. Repeat steps 6 through 14 until the "ZERO" adjustment maintains 0.00 +/- 0.10 Vdc, <u>and</u> the "GAIN" adjustment reflects the contents of the gas cylinder +/- 0.1 ppm of NO₂.
- 16. If a problem occurs while performing this procedure, contact the factory.
- 17. Set the "FAN" and "ALARM" adjustments to the desired activation levels.
- 18. Swing the interior faceplate down, and secure it with the screws removed in step 2. Close the exterior door.

NOTE: Two to three ND-1s may be calibrated with one FCK. The only limitation is the amount of gas contained in the cylinder. Replacement cylinders are available.

RETURN INSTRUCTIONS:

The calibration kit should be carefully packed (well padded) and returned to:

Macurco 3946 South Mariposa Street Englewood, Colorado 80110

1

Please include a note advising the nature of the problem.

Rev: 08/01